CASE STUDY



FEATURING



PROJECT SNAPSHOT

Proiect

• Washington Navy Yard - Steel Lift Station Tank Repair

Tank Specifications

- Material: Steel
- Size: 6 ft. diameter by 20 ft. long
- Age: 60-70 yrs

Tank Condition

• Suffering from severe corrosion and would have suffered catastrophic failure if not replaced or rehabilitated

Environmental Concerns

• Lift Station tank located near Anacostia River - Potential for river contamination without immediate solution

Solution

• Structure Guard® 100% solids epoxy coating to reline and restore

Contractor

· Vortex Services, the installation division of the Vortex Companies

Speed of Repair

• 2 Days

Contacts

- · Matthew Peterson matt.peterson@vortexcompanies.com 801-403-8080
- Brocklyn Stone brocklyn.stone@vortexcompanies.com 303-598-3798

STEEL LIFT STATION TANK **COMPLETELY REHABILITATED USING STRUCTURE GUARD®** 100% SOLIDS EPOXY

Washington Navy Yard Lift Station Tank Rehabilitated with Structure Guard Epoxy to Address Corrosion and Environmental Concerns

SITUATION

The Washington Navy Yard is the former shipyard and ordnance plant of the United States Navy. Located in Southeast Washington, D.C., it is the US Navy's oldest shore establishment. The Yard currently serves as a ceremonial and administrative center for the Navy and is the home to the Chief of Naval Operations, the National Museum of the United States Navy and several other Naval operations.

Located along the Anacostia River, parts of the old Navy Yard's sewer infrastructure were in need of repair to avoid leaking and potential contamination.

In particular, a steel lift station tank was suffering from severe corrosion and would either need to be completely replaced or rehabilitated.







SOLUTION

Several rehabilitation methods and materials were initially discussed. They included hybrid cements, geopolymers and epoxies. After taking a site walk and meeting with the Navy Yard and NICC, the Vortex Services recommended Structure Guard®. Being a manufacturer of a wide range of rehabilitation mortars and epoxies, the Vortex Services team was uniquely qualified to recommend the best possible material application for the project environment. In this case the combination of severe corrosion environment and the tank's proximity to the river, Structure Guard was chosen as the rehabilitation method.

RESULTS

Vortex Services was able to clean, prep and reline the 60+ year-old lift station tank with Structure Guard® Epoxy in two days. Although heavy groundwater infiltration was present, the team was able to work around the problem and complete the installation on time and within budget.

Sensitive to the safety and environmental concerns the US Navy had, Vortex provided an onsite safety compliance manager to ensure the crew was safe and the installation was performed as specified.









GREENBOOK / CITY OF LOS ANGELES DEPARTMENT OF PUBLIC WORKS APPROVES STRUCTURE GUARD

City of Los Angeles Approved Products **Select Lining and Coating**